

Shop: U.S. Auto Inspection

Email: mflautomotivegroup@gmal.com

Address: --

Report ID: MAXIA20240520162646 Test Time: 2024-05-20 16:26:46

Technician: --

# Up to 08/2003 Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

### **Vehicle Information**

Up to 08/2003/Mercedes-Benz/230.475 SL 500/

VIN: WDBSK75FX5F094092

**Customer Information** 

Name: --

**Device information** 

🔁 System Scanned( 23 )

Scanner: MX808 Version: V18.97

Odometer Reading: 65794Miles

License Plate: --

Tel: --

Serial Number: DR7GL9V01387

Repair Order Number: --

System	Status/DTC
ME-SFI 2.8-Motor electronics 2.8	<b>②</b> 0
ETC-Electronic transmission control	<b>Q</b> 3
AB-Airbag	<b>Q</b> 1
SBC-Sensotronic Brake Control	<b>Q</b> 1
ESM-Electronic selector module	<b>Q</b> 1
ABC-ABC active body control	<b>Q</b> 5
EZS-Electronic ignition switch	<b>Q</b> 1
OCP-Overhead control panel	<b>Q</b> 1
LCP-Lower control panel	<b>Q</b> 7
Pass-side SAM-Passenger-side signal acquisition and actuation module	<b>Q</b> 2
Dr-side SAM-Driver signal acquisition and actuation module	<b>Q</b> 7
REAR SAM-Rear signal acquisition and actuation module	<b>Q</b> 6
BNS-Vehicle power supply control module	<b>Q</b> 2
RVC-Rollover bar/vario roof control module	<b>Q</b> 1
PSE-Pneumatic system equipment	<b>Q</b> 2
DCM-L-Door control module left	<b>Q</b> 3
DCM-R-Door control module right	<b>Q</b> 1

Up to 08/2003/Mercedes-Benz/230.475 SL 500/	Test Time: 2024-05-20 16:26:46	Report ID: MAXIA20240520162646
ESA-FL-Electric seat adjustment from	t left	<b>Q</b> 1
ESA-FR-Electric seat adjustment fron	t right	<b>Q</b> 7
SCM [MRM]-Steering column module		<b>3</b>
AAC-Automatic air conditioning		<b>Q</b> 4
HRA-FL-Front left headlamp range co	ontrol	<b>②</b> 0
HRA-FR-Front right headlamp range of	control	<b>②</b> 0
<b>₫</b> DTC ( 59 )		

## ETC-Electronic transmission control (3 DTCs)

DTC	Description	Status
2350	No CAN message was received from control unit N73 (EIS (EZS) control unit).	Stored(Event)
2206	The signal from component WP43 (Output speed sensor (VGS)) is not available.	Stored
2555	The signals of the range selector sensor are implausible in comparison to the signals from the electronic selector lever module.	Stored
2555	lever module.	Stored

#### AB-Airbag (1 DTC)

DTC	Description	Status
9003	The supply voltage of the control module is too low.	Stored (Event)

#### SBC-Sensotronic Brake Control (1 DTC)

DIC	Description	Status
C249E	Undervoltage supply	Stored

# ESM-Electronic selector module (1 DTC)

DTC	Description	Status
P1912	The button signals are implausible.	Stored

#### ABC-ABC active body control (5 DTCs)

DTC	Description	Status
C1525-8	Right rear critical vehicle level	Stored
C1129	Fault in component 'B22/6 (Right rear plunger travel sensor)'	Stored&Current
C1128	Fault in component 'B22/1 (Left rear plunger travel sensor)'	Stored&Current
C1127	Fault in component 'B22/5 (Right front plunger travel sensor)'	Stored&Current

AUTEL usautoinspection.com

MX808 Page 2

Up to 08/2003/Me 500/	rcedes-Benz/230.475 SL	Test Time: 2024-05-20 16:26:46	Report ID: MAXIA2024052016264
C1126	Fault in component 'B sensor)'	22/4 (Left front plunger travel	Stored&Current
EZS-Electronic	ignition switch (1 DTC)		
DTC	Description		Status
B1010	Undervoltage supply		Stored (Event)
OCP-Overhead	control panel (1 DTC)		
DTC	Description		Status
B1020	Terminal Kl.12VOUT h	as Short circuit.	Stored
LCP-Lower con	trol panel (7 DTCs)		
DTC	Description		Status
B1183-4	Switch 'N72s22 (Towifaulty or is operated for	ng Sensor (TS/AS) off switch)' is or over 25s.	Stored
B1178	Switch 'N72s14 (ESP over 25s.	off switch)' is faulty or is operated for	Stored
B1179	Switch 'N72s20 (Activis faulty or is operated	e Body Control (ABC) Sport switch)' I for over 25s.	Stored
B1180	Switch 'N72s18 (Level operated for over 25s.	setting switch)' is faulty or is	Stored
B1119	Switch 'N72s7 (Exterior or is operated for over	or mirror adjustment switch)' is faulty 25s.	Stored
B1074		ication with the control module 'N73 ritch (EIS/EZS) control module)'.	Stored (Event)
B1010		component 'N72 (Lower Control rol module)' is too low.	Stored
Pass-side SAM	-Passenger-side signal ad	equisition and actuation module (2 DTC	s)
DTC	Description		Status
B1026		Automatic A/C (AAC/KLA) control o' is not sending data on the CAN	Stored (Event)
B1010	The supply voltage of	the control module is too low.	Stored (Event)
Dr-side SAM-D	river signal acquisition and	d actuation module (7 DTCs)	
DTC	Description		Status
B1338-001	B12/2 (Refrigerant pre Refrigerant pressure ) has Short circuit.	essure and temperature sensor 1) ( The component is faulty or the wire	Stored
B1076		3 (Rear SAM (Signal Acquisition and not sending data on the CAN bus.	Stored (Event)
B1074		Electronic Ignition Switch (EIS/EZS) t sending data on the CAN bus.	Stored (Event)

Up to 08/2003/M 500/	ercedes-Benz/230.475 SL Test Time: 2024-05-20 16:26:46	Report ID: MAXIA2024052016264
B1026	Control module 'N22 (Automatic A/C (AAC/KLA) control and operating module)' is not sending data on the CAN bus.	Stored (Event)
B1018-001	The supply voltage of the control module is implausible.	Stored (Event)
B1010	The supply voltage of the control module is too low.	Stored (Event)
B1342	The input signal of terminal 15 is not OK	Stored
REAR SAM-Re	ar signal acquisition and actuation module (6 DTCs)	
DTC	Description	Status
B1619	Component 'E3e9 (Left stop lamp, tail lamp and parking lamp)' in module 'E3 (Left tail lamp)' is faulty.	Stored
B1620	Component 'E4e9 (Right stop lamp, tail lamp and parking lamp)' in module 'E4 (Right tail lamp)' is faulty.	Stored
B1621	Component 'E21 (Center high mounted stop lamp)' is faulty.	Stored
B1627-001	Component 'Trunk lamp' is faulty.( Right )	Stored
B1026	Control module 'N22 (Automatic A/C (AAC/KLA) control and operating module)' is not sending data on the CAN bus.	Stored (Event)
B1010	The supply voltage of the control module is too low.	Stored (Event)
BNS-Vehicle p	ower supply control module (2 DTCs)	
DTC	Description	Status
B1828	Component 'K57 (Battery isolating relay)' is faulty or no terminal 61.	Stored
B1829	Component 'Fuse for starter battery circuit' is faulty.	Stored
RVC-Rollover b	par/vario roof control module (1 DTC)	
DTC	Description	Status
B1010	The operating voltage is out of the permissible range. The voltage was below 8.0V during 1s.	Stored (Event)
PSE-Pneumati	c system equipment (2 DTCs)	
DTC	Description	Status
B1442	For the following pneumatic branch, the safety time of the power closing is exceeded. Trunk lid	Stored
B1440-14	The maximum operating time for switch S62/21 (Trunk lid Keyless Go (KG) button) is exceeded.	Stored
DCM-L-Door c	ontrol module left (3 DTCs)	
DTC	Description	Status
B1010	The operating voltage is out of the permissible range. The voltage was below 8.5V during 1s.	Stored (Event)

Page 4

AUTEL usautoinspection.com

MX808

Up to 08/2003/Me 500/	ercedes-Benz/230.475 SL Test Time: 2024-05-20 16:26:46	Report ID: MAXIA20240520162646
B1206	Signal from the component 'M21/1r2 (Mirror adjustment up/down potentiometer)' is faulty.	Stored
B1208	Signal from the component 'M21/1r3 (Mirror in/out adjustment potentiometer)' is faulty.	Stored
DCM-R-Door c	ontrol module right(1 DTC)	
DTC	Description	Status
B1010	The operating voltage is out of the permissible range. The voltage was below 8.5V during 1s.	Stored (Event)
ESA-FL-Electri	c seat adjustment front left(1 DTC)	
DTC	Description	Status
B1200-007	M27m1 (Forward/back motor): The current measurement for the obstruction protection provides implausible values during the Easy Entry function.	Stored
ESA-FR-Electri	c seat adjustment front right (7 DTCs)	
DTC	Description	Status
B1006-003	No normalization of the backrest adjustment.	Stored&Current
B1006-005	No normalization of the head restraint adjustment.	Stored
B1006-004	No normalization of the inclination adjustment.	Stored
B1006-002	No normalization of the seat cushion depth adjustment.	Stored
B1006-001	No normalization of the height adjustment.	Stored
B1006-000	No normalization of the forward/back adjustment.	Stored
B1211	Signal from the component 'A60 (Vehicle sensitive seat belt lock sensor)' is faulty.	Stored
SCM [MRM]-St	eering column module (3 DTCs)	
DTC	Description	Status
B1327-000	Component 'S59/1 (Steering column adjustment/steering wheel heater switch)' is faulty.	Stored
B1331-000	Component 'S111s3 (Accept/terminate phone call button)' is faulty.	Stored
B1333-000	Component 'S110s3 (System selection button)' is faulty.	Stored
AAC-Automatic	c air conditioning (4 DTCs)	
DTC	Description	Status
B1453-002	M16/21 (Fresh air and recirculated air flap actuator motor)Mechanical fault	Stored
B1010-001	The supply voltage of the control module is too low.	Stored (Event)
B1022-000	Fault in CAN communication with the control module 'Left front Electric Seat Adjustment (ESA/ESV)'.	Stored (Event)

Page 5

**AUTEL** usautoinspection.com

MX808

Up to 08/2003/Mere 500/	cedes-Benz/230.475 SL	Test Time: 2024-05-20 16:26:46	Report ID: MAXIA20240520162646
B1055-000	Fault in CAN communication 'DCM-L (Left Door Control		Stored (Event)

_							

					-						-	
$\sim$	$\sim$	h	n	п	$\sim$ 1	$\sim$	n	N	ı	$\sim$	tn	•
 ᆮ	u			п	u	а		- 11	٧	u	te	. 3

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



JTEL usautoinspection.com MX808 Page 6